Application Note: GateManager 8250 ShellShock fix

8

This document guides you through how to fix the so called "ShellShock" vulnerability on Linux.

Version: 1.1, 2014



1. What is shellshock

When writing this note, there is a lot of talking about a vulnerability in the linux OS given the name shellshock. This exploit utilizes the "bash" program installed on most linux systems and it can give hackers access to the Linux OS.

2. Is GateManager vulnerable

The GateManager 8250 server software itself is not affected by this vulnerability, but the server - as a whole - could be vulnerable to the ShellShock exploit, since it is running on a standard Linux system (typically CentOS if you are using a pre-packed Secomea VM image).

Whether the server is actually vulnerable (for external attacks) depends on whether you have enabled other services on the Linux OS (such as Apache web server or SSH), and how well it is shielded from the Internet by firewalls etc.

3. How to add the patch

The GateManager server need to be able to access the internet to download the patch. This is normally the case and there for not covered her. If the command (yum) shown below will fail it is probably the internet access that fail.

3.1. Test to see if your Linux installation is affected:

> env test='() { ignored;}; echo "Vulnerable"' bash -c true

3.2. Fix the problem with the command:

yum update bash (it is not recommended to leave out the hash unless you know what you are doing)

014 i686 i680 [root@gm51 /] [Vulnerable [root@gm51 /] Loaded plugin	ecomea.com 2.6.32 6 i386 GNU/Linux]# env test='() { 1 yum update bas ns: fastestmirror astect i rocks 2 A A A A A A			2
Package	Arch	Version	Repository	Size
Updating: bash Transaction 3	i686 Summary	4.1.2-15.el6_5.2	updates	887 k
<pre>Transaction Summary </pre>				

Application note, GateManager 8250 shellshock fix Version: 1.1 2014

secumea

4. Notices

Publication and copyright

Version 1.1, 2014

© **Copyright Secomea A/S 2014**. All rights reserved. You may download and print a copy for your own use. As a high-level administrator, you may use whatever you like from contents of this document to create your own instructions for deploying our products. Otherwise, no part of this document may be copied or reproduced in any way, without the written consent of Secomea A/S. We would appreciate getting a copy of the material you produce in order to make our own material better and – if you give us permission – to inspire other users.

Trademarks

GateManager^M is trademark of Secomea A/S. Other trademarks are the property of their respective owners.

Disclaimer

Secomea A/S reserves the right to make changes to this publication and to the products described herein without notice. The publication of this document does not represent a commitment on the part of Secomea A/S. Considerable effort has been made to ensure that this publication is free of inaccuracies and omissions but we can not guarantee that there are none.

The following paragraph does not apply to any country or state where such provisions are inconsistent with local law:

SECOMEA A/S PROVIDES THIS PUBLICATION "AS IS" WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTA-BILITY OR FITNESS FOR A PARTICULAR PURPOSE

Secomea A/S shall not be liable for any direct, indirect, incidental, consequential, or other damage alleged in connection with the furnishing or use of this information.

Secomea A/S Denmark

CVR No. DK 31 36 60 38

E-mail: sales@secomea.com www.secomea.com



Page 3 of 3